



CARROLL DANIEL
CONSTRUCTION



**MILLSIDE ELEMENTARY SCHOOL
PROGRESS REPORT
OCTOBER 4, 2016**



STRATTON
CONSTRUCTION SCHEDULING & SEQUENCING

509 CROWE DRIVE
HIGHLANDS, NC 28741
404.944.5298

**Millside Elementary School Progress Report
October 4, 2016**



East Gym Elevation



Gym Roof Joists



Gym Structure



West Tower Elevations

Millside Elementary School Progress Report
October 4, 2016



South Tower Elevation West End



East Tower Elevation



Tower Roof East



Tower Roof West

**Millside Elementary School Progress Report
October 4, 2016**



Kitchen - Dining Roof Deck



Kitchen Structure



Area B Inwall Plumbing



Area D Demising Wall